

PARAJET SAFETY ADVISORY BULLETIN

SEPTEMBER 2023 - LITE TRIKE BADGE



Please read and follow this safety advisory bulletin thoroughly before undertaking further product use or flight. This advisory bulletin contains important safety information and disregarding these precautions could cause serious injury or death.

We have produced the following safety bulletin as part of our commitment to our customers' safety and continued enjoyment of our sport.

To ensure the continued safe operation and optimal configuration of your equipment, please continue reading to the end of this document. By receiving this safety bulletin, you will be taken to have read and understood it in full.

In addition, all pilots are reminded of the importance of carrying out comprehensive pre and post flight checks of their paramotoring equipment and this safety advisory bulletin has been issued to inform pilots of recommended additional safety measures that must be undertaken.

PRODUCT

Parajet Maverick Lite Trike [PJ-A-11184]



SITUATION/CONCERN

A customer has advised us that his decorative Maverick badge (please see picture) has come detached from his trike frame and indicated a concern that this could cause a safety issue were it to come off during flight.



SOLUTION/PROCEDURE

With this in mind and safety always being a top priority, we are issuing the following advice to all Lite Trike customers:

- The Maverick badge is fastened using a strong adhesive and is merely decorative in function.
- In the interest of safety all customers are advised to perform regular pre-flight inspections, and should there be any doubt, they are advised to remove it and confirm with us info@parajet.com so we can prepare and send them a sticker alternative.

FURTHER ASSISTANCE

If you are ever unsure as to the correct configuration, condition, or safe operation of your equipment please always ensure you seek appropriate advice from us before any further use.

Having provided you with notice of the required checks and adjustments above, Parajet shall have no liability whatsoever in respect of any subsequent accident or injury resulting from your failure to adhere to the information and instructions provided in this safety bulletin.